



<b>TABS Pool Restrictions - Tolerances</b>	<b>ETX</b>	<b>STX</b>	<b>WLA</b>	<b>ELA</b>	<b>M1-24"</b>	<b>M1-30"</b>	<b>M2-24"</b>	<b>M2-30"</b>	<b>M3</b>
TABS Pool - Length	2% or 2,000	2% or 2,000			0.2% or 100		0.2% or 100		
TABS Pool - Short	2% or 1,500	2% or 1,500	2% or 1,500	2% or 1,500	2% or 1,500	2% or 1,500	2% or 1,500	2% or 1,500	2% or 1,500

**No-Notice Restrictions**

**OFO / Imbalance Notice**

System Wide OFO	M2-24, M2-30 and M3 no DP OFO issued January 6, 2022. 2,000 Dth / 2% Tolerance
Customer Specific OFO	---
Imbalances Warnings	Stay Balance - STX, ETX, WLA, ELA, M1-24 and M1-30

**FERC Order 698**

---

**Systemwide Notes:**

If customers/point operators do not manage hourly takes from the system, it will lead to delivery pressures being lower than desired for this area. As a result, TE may be required to impose further restrictions or courses of action in order to maintain the operational integrity of the system, including but not limited to, implementation of flow control at specific delivery meter locations.

TE may be required to issue hourly OFO's to impose further restrictions in order to maintain the operational integrity of the system.

Please contact your Operations Account Representative should you have any questions.